

## UPDATE VERSION: "V5B8A306"


### 1 FEATURE IMPROVEMENTS

Fixed an issue where the system does not allow iPhone battery charging via USB port.

### 2 INSTALLATION INSTRUCTIONS

To check the installed version of software please perform the following procedure when the unit is off:

- 1 - Press sequentially: **▶▶, ◀◀, ▶▶, ◀◀, ▶▶, ◀◀**
- 2 - The system will display the installed SW version for a few seconds on the screen.



### 3 PREPARATION

You need a blank USB flash drive that has a capacity in between 256MB and 64GB. Ensure the USB Flash Drive is formatted to FAT32.

- a. Please download the update file from this link
- b. Please unzip on your computer the folder named "HMR 10 D\_update\_file\_V5B8A306.zip"

### 4 INSTALL PROCESS FOR USB UPDATE

**ATTENTION:** before start the USB update please take care of the following indications:

- Please check that the power supply voltage is over 12Vdc and make sure that it stays over this level for the whole procedure time.
- Please don't shut off the unit during the update procedure.
- Please don't remove the USB flash drive while the update procedure is running.

1. Copy the .MVA\* file into an empty USB flash drive (see "Preparation" above).  
\*The file name to copy is: "yst8064\_310D\_mtk662x\_DAB\_V5B8A306(HERTZ MARINE+HMR 10D).mva"
2. Turn on the HMR 10 D.
3. Connect the USB flash drive. The update procedure starts automatically after a few seconds.
4. The system will inform that the update procedure is started by displaying "update" on the screen.
5. Wait until the system informs that the update procedure is finished and successful. The system will display "SUCCESS" on the screen.
6. Please shut off the system.
7. Then remove the USB flash drive.
8. To check the current system SW version please see "Installation instructions" in the above paragraph.