

“Traditional Houses in Western Kosovo: A Descriptive Survey of Kullas in the Municipalities of Istog and Klina.”

Sahar Rassam, Architect

Table (1): Istog Kullas: Condition at time of Survey and damage assessment, August-September 2000.

Village or city in Istog	¹ Kulla of	Year built	Condition of the kulla	Construction material		No. Of floors	Cause of damage		Inhabited	Self maintained	Alterations made
				stone	brick		conflict	neglect			
Caralluke	G.Papaj		Demolished to be replaced by a new house	*		2	*	*	n		
Cerçe	H.H.Hasani	1870	Only exterior walls remain	*		2	*		n		
	I.A.Rexhaj	1891	Most exterior walls remain	*		2	*		n		
	I.Haskaj	1875	Exterior walls with cracks remain, unrecognized as a kulla	*		2	*		n		complete
	I.Z.Rexhaj	1890	Completely destroyed			2	*		n		
	T.Kada	1870	Completely destroyed			2	*		n		
Gjurakoc	A.Fetahaj	1852	Walls in good condition Needs restoring of interiors & roof	*	*	3		*			
	M.Gega	~200 year old	Damage in a side wall. Roof & interiors need restoring	*	*	3		*	n		
Istog city	J.B. Buleshkaj	1850	Walls have cracks Roof and interior damaged	*		3		*	n		
	I.S.Bytyqi	1750	Exterior walls with cracks remain	*		2	*		n		windows
Kaliqan	U.S.Ukaj	1850	Small damage in rear wall Roof needs restoring	*		3	*	shelled	n		

¹ The names of the kullas are of their present owners or of their previous owners or builders.

Village or city in Istog	Kulla of	Year built	Condition of the kulla	Construction material		No. Of floors	Cause of damage		Inhabited	Self maintained	Alterations made
				stone	brick		conflict	neglect			
Liukavc of Beg	H.D.Asllanaj	~100 year old	Rear wall damaged Cracks in walls, more like a house than a kulla		mud bricks	2		*	n		
	R.M.Visoqi	1872	Outer walls remain	*		2	*		n		All windows
	A.Beqiri	1878	Completely destroyed			3	*		n		
Lubozhda	E.Z.Dautaj	1895	Three exterior walls remain	*		2	*		n		
	J.M.Idrizaj	1885	Exterior walls with cracks remain	*		2	*		n		
	K.Fazlia	1867	Exterior walls remain	*		3	*		n		
Mojstir	A.B.Zekaj	1870	Part of walls with cracks remain	*		2	*		n		windows
Orroberde	Z.S.Hakaj	1820	Two walls remain	*		2	*		n		
Prekalle	I.M.Osmanaj		Two walls are damaged	*		3	*		n		
Shushice e Eperme	R.Brahimi	1870	Parts of walls remain	*		2	*		n		
	Z.Selmani	1890	Only front wall with part of a side wall remain.	*		2	*		n		
	N.Kadria	1885	One side completely destroyed	*		2	*		n		Some windows
	H.Syla	1905	Completely destroyed	*		2	*		n		
Shushice e Ulet	F.A.Meta	1850	Lower floor walls remain	*		2	*		n		
	R.H.Salihaj	1902	Exterior walls remain, used as a school for 20 years	*		2	*		n		windows
	R.A.Ademaj	1875	Part of walls with major cracks remain	*		2	*		n		

Village or city in Istog	Kulla of	Year built	Condition of the kulla	Construction material		No. Of floors	Cause of damage		Inhabited	Self maintained	Alterations made
				stone	brick		conflict	neglect			
Staradran	B.M.Mavraj		Needs restoring of roof & interiors	*	*	3		*	y		Some windows
	H.I.Elshani	1875	Exterior walls remain	*		2	*		n		
Syne	A.Avdia	1820	Exterior walls remain	*		2	*		n		
	R.M.Avdijaj	1870	Only front wall remains	*		2	*		n		
Tomoc	N.A.Shatri	1890	Self reconstructed	*		3 up to 1922 later 2	*		y	*	Windows, interiors & plastered
	S.Shatri	1905	Exterior walls remain		*	2	*		n		Some windows
	M.R.Shatri	1910	Completely destroyed			3	*		n		
Trubuhovec	H.H.Osmanaj	1850	Some cracks & roof needs repairing	*	*	3	*		y		
	M.Z.Osmanaj	1850	Roof,& interior and parts of walls need restoring.	*		3		*	n		
Uce	J.Muzliukaj	1878	One side destroyed	*		3	*		n		
	Z.Selmanaj		Rear side destroyed & cracks on walls	*		3		*	n		
	H.Muzlia	1882	Most exterior walls remain	*		2	*		n		
	R.Alia	1914	Completely destroyed			2	*		n		
	C.Bajraktari	1910	Completely destroyed			2	*		n		
	A.T.Imeraj	1870	Completely destroyed			2	*		n		
	H.Hiti	1890	Main elevation destroyed & another house was built next to it blocking the windows				*	*	n		

Village or city in Istog	Kulla of	Year built	Condition of the kulla	Construction material		No. Of floors	Cause of damage		Inhabited	Self maintained	Alterations made
				stone	brick		conflict	neglect			
Vrelle	A.Vuthaj	1877	Exterior walls with cracks remain	*		3	*		n		
	S.F.Dreshaj	1890	Some damages in roof and walls, looks more like a house	*		2	shelled		n		Windows
	S.B.Dreshaj	1892	Walls are relatively in good condition	*		2		*	y		
	T.A.Bicaj	1877	Outer walls remain with some cracks	*		2	*		n		Few windows
	S.O.Bicaj	1879	Good condition	*		3		*	y	*	Few windows
Zabllac	C.A.Ahmetaj	1928	A corner destroyed from shelling		*	3	* shelled		n		

Table (2): Klina Kullas: Condition at time of Survey and damage assessment, August-September 2000.

Village or city in Klina	Kulla of	Year built	Condition of the kulla	Construction material		No. Of floors	Cause of damage		Inhabited	Self maintained	Alterations made
				stone	brick		conflict	neglect			
Doberdol	S.Mata	18 th cent.	Walls were falling apart. Roof replaced with metal sheets. Had nice cardak like cantilever.	*		2	*	*	n		
Grabanice	Bardhec	19 th cent.	Upper floor needs restoring		*	3	*		y	*	Some windows, interiors & new entrance
Gramnik	H.Maxharraj	~100 year	In good condition	*		2			y		
	S.Gashi	1910	Roof, some walls & upper floor are damaged	*		2	*		n		Windows, extra room
	H.Merlakv		Completely destroyed						n		
Poterce e Eperme	R.Zendi		One wall & roof damaged, cracks on other walls		*	3	*		n		Some windows enlarged
Ranoc	J.M.Jaku	1942	In good condition		*	2			y		Built with larger windows
Sferke	I.Gashi	1932	Damages in walls and roof	*		2	*		y		
Siceve	I.F.Rraci	~100 year	Parts of walls remain	*		2	*		n		